
User-Guide

mEggBot





Contents

Is .	Equipment necessary before
115	Product description
1.	mDrawBot
III.	Mechanical assembly (see document mDrawBot instruction V1.1 20150704) 1
IV.	Recommended wiring diagram (Bluetooth communication for Bluetooth version). 2
٧、	Definition of mEggBot electronic wiring
VI.	mDraw software
1.	Description of mDraw functions
2.	Software installation,
3.	Button function of main software interface
4.	Use of mEggBot6
VII、	Example of completely using mDraw software
VIII、	Please see "How to use inkscape+corelDRAW software" for generation of SVG
graph	file
IX、	Refer to HYPERLINK mDrawBot FAQs - V1.3(English) for FAQs
X、	Contact us: 12



I. A Equipment necessary before

- 1. Hardware:
 - ①.mDrawBot kit
 - 2. Assemble Instruction V1.1 20150704
- 2. Software:
 - a. Necessary software
 - **■** mDraw
 - **Inksape**
 - B. Software possibly required
 - Arduino IDE
- Makeblock main board drive (Note: If Mac OS system is used, click hyperlink to load and install the drive)
- 3. Download software and detained information package



http://learn.makeblock.cc/mdrawbot/

Hint 1

4 assembly modes are used for mDrawBot, the assembly of all movable parts has assembly accuracy requirement, install and finely adjust the robot strictly as required by the assembly description, especially adjustment of shaft and rotating part, steering engine and rudder arm, machine levelness.

Hint 2

The material object may differ from the picture provided in the specification, so the specification is only for reference, and specification and software may be changed without prior notice. Please assess the website for detailed change: http://learn.makeblock.cc/mdrawbot/




II. Product description

1. mDrawBot

mDrawBot is advanced drawing kit designed based on Makeblock open platform and may be constructed to four types: mScara, mSpider, mEggBot and mCar. In addition to specially designed hardware structure, we specially equip mDrawBot software — mDraw.

A. mEggBot

A drawing robot able to draw beautiful pattern on egg or other cylinder or spheroid



III. Mechanical assembly (see document mDrawBot


instruction V1.1 20150704)




IV Recommended wiring diagram (Bluetooth

communication for Bluetooth version)

(Note: When Bluetooth is used as serial port, connect Bluetooth with port 5 OF Makeblock Orion board.



V. Definition of mEggBot electronic wiring





VI mDraw software


1. Description of mDraw functions

mDraw is open source cross-platform software produced by Makeblock and support Windows system, Mac system and Linux system, and perfectly supports four types of mDrawBot such as mSpider, mScara, mEggBot and mCar, and supports the steering engine mode and laser mode of Makeblock XY drawing robot kit V2.0.

Support SVG format, Change BMP to SVG

2. Software installation,

Unzip the downloaded file pack, find and double click the file as show in the figure.



3. Button function of main software interface




new

(1) Main interface

Back to origin point

Drop-down box of robot configuration



(2) Button function

- : Open the file
- : Delete SVG file
- : Begin/ suspend
- : Stop
- : Up and down mirror image
- : Left and right mirror image
- : Clockwise rotate at 90°
- : Anticlockwise rotate at 90°
- Help link



: Machine returning to initial position

"Scaro": Robot mode switching button: five modes such as mScara, mSpider, mEggBot, mCar,

XY

: Setting button, mainly used for setting arm length parameter, operation speed, and front
and reverse rotation of motor

Update Firmware: Upgrade firmware button

Wire: Electronic wiring diagram of robot

Pen Up 130 : Pen lift parameter setting

Pen Down : Pen fall parameter setting

Save: Store pen lift and fall parameters on the main board chip

COM1 : Select serial port


Connect: Serial port connecting button

Sync Position (G92): Synchronous position

Scale: 1.0 : Change drawing scale


(3) Function description of plot area

a) After double clicking the main interface, the robot will move with the graph.





- b). Drag the led SVG format to change the size and location of the SVG drawing, or change the drawing size by directly entering the digit on the low right of the graph.
- c). While leading BMP file, the software automatically pop up SVG file change dialog box, and according to adjustment parameter, change the file to SVG format.




4. Use of mEggBot

(1) mEggBot


- a) . Inspect and confirm that the wire connection is correct (Note: you may click with the inspect.). Connect USB with the computer (Note: if Bluetooth is used, install the Bluetooth drive on the computer)
- b) . Select and connect correct COM port and click burning hardware (note: While the robot is switched to other drawing type, you are required to click Update Firmware to upgrade the firmware to ensure The robot can operate in new drawing type.





c) .Single click the icon to access the setting interface Under general condition, default setting is used. When you find that drawing direction is incorrect, modify the selection direction of stepping motor, and click Ok to confirm.


Meaning of axle view and software parameter




d) . Setting of steering engine pen lift and fall parameter

As shown in the figure, respectively enter the value by Pen up and Pen Down of the software, click PenUp and PenDown. When the following effect is observe and obtained, it is possible to set pen lift mechanism of the steering engine (note: If the rudder arm of the steering engine does not have the following angle, remove the rudder arm by a cross screwdriver to adjust installation angle, the rubber band is adjusted for degree of tightness according to requirement, and pendown is subject to just contact with the paper.








Note: Software default value is here, and the value is subject to the value set during debugging during use.






f) . After setting the parameter, turn off the power switch on the main board, manually reset the mEggBot to initial position, turn on the power switch on the main board, and click the button






- 1. As the test is passed as described above, mEggBot can operate smoothly. You may draw complex graph.
- 2. Automatically or manually reset mEggBot to initial position. (_____ensure that the serial port is properly connected, the parameter of the pen lift mechanism is correctly set, and the power supply is properly connected.



3. lead SVG graph, for example, \mDrawBot Download Package\Examples of Material\mEggBot\facial expression\1.svg, as shown in the following figure.





4. Click the button of mDraw software mEggBot begins to work. When the machine stops operation, the graph has been drawn. The drawing effect is shown below:



VIII、 Please see "How to use inkscape+corelDRAW software"



for generation of SVG graph file.

IX、 Refer to HYPERLINK <u>mDrawBot FAQs - V1.3(English)</u> for FAQs.

X Contact us:

support@makeblock.cc
https://www.facebook.com/Makeblock?ref=br_tf
https://plus.google.com/102486511775733872783/posts
https://twitter.com/Makeblock

Makeblock! Construct Your Dreams!