



Rolling Gas-Lift Sit-Stand Desks





P/N 30904, 30905, 30906





Installation Guide





	Dx8	M6x16mm		Ex1	M8X20
	Fx4			Gx1	4MM
	Hx1	5MM		Ix1	
	Jx1	17MM		Kx1	
	Lx2	M6x12mm			

1



Dx8




Lx2




Gx1

2



Kx1



Ex1




Ix1




Hx1

3



Fx4




Jx1


4




USER GUIDE



CAUTION: Do not exceed the maximum listed weight capacity when raising the desk. Serious injury or property damage may occur



Pull the lever upwards to raise the desktop.



Pull lever upwards and apply pressure downwards on the desktop surface to lower the desktop.